



STAR ONLINE PUBLICATION



Case Number: S2018000012

Release Date: 11/06/2020

Symptom/Vehicle Issue: Check engine lamp on. Fault code P0244-TURBOCHARGER/SUPERCHARGER WASTEGATE SOLENOID "A" RANGE/PERFORMANCE is set in the Powertrain Control Module (PCM a.k.a. ECM) after the turbocharger assembly has been replaced.

Discussion: If P0244 has set in the PCM after replacing the turbocharger assembly, replace the PCM.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found